

Fax 860-496-9017 www.waringcommercialproducts.com


т11 (("	D 4#	A A G. A STI HIGG DITH LET CHAIN GOOD CENTRAL	
Illustration#	Part#	Description	
1	028769-E	Jar Lid Cover	
2	028768	Vinyl Jar Lid	
3	503345	Blade Assembly	
4	024271	O Ring	
5	026798	Support Washer	
6	026648	64 oz. Stainless Steel Container	
7	026649	Container Support	
8	026797	Bearing Holder Gasket	
9	026796	Bearing Holder Washer	
10	026795	Stainless Steel Jar Bearing Holder Nut	
11	503601 503604 028538	Sq. Drive Coupling with Adapter (on units after 3/29/2022) Sq. Drive Coupling with Adapter 2 Gen. (changed after 1;/3/2021) Drive Coupling	
12	026442	Jar Pad	
13	035399 028824	Leili Motor with Sensor (on units after 8/28/2017) ECM Motor with Sensor	
14	038278 026437	Dampening Plate Gasket (on units after 8/25/2022) Dampening Plate Gasket	
15	503382-E-67 503382-E	MX Housings, Ferrite Core & Cord (on units after 8/28/2017) MX Housings, Ferrite Core & Cord (on units after 12/10/2012)	
16	028541	Motor Foam (2 required)	
17	026439	Dampening Plate Bushing (4 required)	
18	038486 026453	Dampening Plate Sleeve (4 required on units after 8/25/2022) Dampening Plate Sleeve (4 required)	
19	026459	Washer (2 required)	
20	028929	Sems (4 required)	
21	036401	Control Panel with Interlock (XPrep changed after 8/24/2018) comes with switches-key board-main board-filter board	
	035024 028568	Soft Start Control Panel (XPrep use 036401) Control Panel (Xtreme use 035024)	
22	028248	Top Housing Foam Rear Baffle	
23	028249	Top Housing Foam Front Baffle	
24		Motor Housing is Included with Illustration# 15	
25	034900	PCB Cushions (4 required on units after 7/18/2019)	
26	037232	Washer (2 required)	
27	037007	PCB Mounting Bracket (2 required)	
28	013768	Screw (2 required)	
29	028247	Bottom Housing Foam Baffle	
30	028542		
31		led with Illustration# 15	
32	002943	Washer (4 required)	

Catalog Model MX1200XTEES MX1200XT31CE MX1200XTSEES MX1200XT32CE

Waring Factory Service Center 314 Ella T. Grasso Ave. Torrington, CT 06790 Tele. 1-800-269-6640

Fax 860-496-9017 www.waringcommercialproducts.com

Illustration#	Part#	Description
32	002943	Washer (4 required)
33	013731	Cable Tie (3 required)
34	007556	Strain Relief
35	Bottom Housi	ing is Included with Illustration# 15
36	012505	Screw (4 required)
37	026430	Corner Post (4 required)
38	028928	Sems (4 required)




033484 Brush/Spring



Parts No Longer Used

(Last used on 12/10/2012)




Sq. Drive Adapter

503604 Sq. Drive Coupling with Adapter 2 Gen.

503601

Sq. Drive Coupling with Adapter



Catalog MX1200XTEES MX1200XTSEES **Model** MX1200XT31CE MX1200XT32CE



